
Memorandum

Document Control Number: mm004

Date: 5/2/ 2013

To: Heidi Davis – MassDEP, Brad Chase- DMF - Thomas Russo

CC: Frank Tramontozzi-COQ, Rob Stevens-COQ, David Mariano-FST, Tom Russo-FST, Dean Groves

From: Paul Bergquist - Environmental Monitor

Subject: Town Brook Enhancement Project - Quincy – Site Visit 4.17.13

A site visit was conducted on Wednesday, April 17, 2013 to review the status of construction, observe the condition of the channel and substrate. Lucas Environmental had just completed the egg monitoring and noted that smelt eggs were more dense at Transect #1 (west end of Channel) and not present at Transect 3. With major activities complete the remaining major item to complete is the BVW planting along the edge of the channel and in the island. It is noted that the Environmental Monitoring Plan was resubmitted on 5/2/13 incorporating the protocols discussed with Brad Chase The following observations are noted:

1. Top on existing channel wall adjacent to new channel wall has been restored see picture 11-1). Abutting properties restoration in process, pavement installed both sides of channel, see picture 11-2



Picture 11-1 – Existing Wall Restoration Station 19+50



Picture 11-2 – Abutting Properties Restoration – Pavement

2. Island Area remains stable, planting to occur in June. Town Brook flow is clear. See Picture 11-3.



Picture 11-3 – View of BVW Island.

3. Surface restoration of the sidewalk continues including utility work. See picture 11-4



Picture 11-4 – Sidewalk Restoration and utility work.

4. Park Area, Station 24+50 to 23+00 Terraced vegetative planting area nearing completion, plantings required. Surface restoration in process. See Picture 11-5



Picture 11-5 – Park Area restoration in process.

End of Memo